







the threaded spindle and the nuts have stickers with numbers
 insert the threaded spindle in the two nuts as shown in the diagram
 screw the threaded spindle in both nuts simultaneously




EZCL/1-1 threaded spindle




EZCL/1-2 left nut



EZCL/1-3 right nut



EZCL/1-4 frame



EZCL/1-5 fastening of frame



EZCL/1-7 crank